MSIGNODE[®] For reference only

Steel strap

Coil winding

Signode strapping is produced in two basic coil windings:

Mill wound

The strapping is oscillated uniformly and tightly across the 2-1/2" (63.5 mm) width of the coil.

Ribbon wound

Each layer is wound directly over the one below it so that the width of the strapping is the width of the coil.





Mill wound

Ribbon wound

Coil sizes

strap size.

Inside diameter: 16" (406.4mm)

Outside diameter: Mill wound coils measure 23" (584.2mm). Ribbon wound coils vary from 23-1/2" to 27" (596.9mm to 685.8mm) depending on

Standard multi-coil skids

Twelve mill wound coils make up a standard skid. The number of ribbon wound coils will vary with strapping width.





Ribbon wound skid

Mill wound skid



Anchor strapping

The standard or stocked version of punched strapping comes in two sizes: 3/4" x 0.017" (19.0 x 0.43 mm) Apex Plus with in-line 0.145" (3.5 mm) holes on 3/4" (19.0 mm) centers and a strap strength of 1,255 lbs. (5 583 N).

1-1/4" \times 0.029" (31.8 \times 0.74mm) Magnus with staggered 0.240" (6.1mm) holes on 1-1/2" (38.1 mm) centers and a strap strength of 4,020 lbs. (17 881 N).

Standard strap finishes

Signode produces three different steel strapping finishes. Each is tailored to the requirements of particular tensioning methods, sealing devices and packaging applications.

Painted

Painted strapping is coated to offer corrosion resistance. Available in a wide range of Magnus strapping sizes, it is used in crimp-type seal systems to produce high joint strength.

Painted and waxed

Painted and waxed strapping also provides corrosion resistance. Available in all Apex Plus and Magnus strap sizes, it can be used in notch or crimp-type seal systems. Its primary advantage is improved tension transmission around load corners.

Waxed strapping is required for feedwheel-type tensioners.

Zinc painted and waxed

Zinc finish strapping is waxed and has a zinc-enriched coating to provide outstanding resistance to rust. Available in a variety of Apex Plus and Magnus sizes, it has the same improved tension transmission characteristics as the painted and waxed strapping. Zinc finish protects where it is needed most—at points of surface damage and scratches.

Sealless joint types

Sealless joints can be made with Signode manual or pneumatic combination tools. Using interlocking keys, the sealless joints provide static joint strength equal to that of notch-type joints. The reverse lock sealless joint features one reversed interlocking key for added security in impact conditions.



Three key sealless joint



Four key, reverse lock, sealless joint

Basic seal joint types Notch joint

One way to lock strap ends is to cut, or "notch" the seal and the strapping it joins to form tabs at the edges. These tabs are bent down (down notch joint) or bent up (reverse notch joint). The strength of the notch joint comes from the mechanical interlock between the seal and strapping. Notch joints are typically used on waxed strapping in packaging and unitizing applications.



Down notch joint



PACKAGE SURFACE



Crimp joint

Another way to seal the ends of strapping is to press or "crimp" undulations into the seal and strapping ends. The strength of the crimp joint comes from the deformed seal creating high frictional forces. Crimp joints produce high static and dynamic joint strengths and are used on applications like carloading in which the strapped load is subject to severe impact.



PACKAGE SURFACE

Steel Strapping

For uncompromising quality and packaging effectiveness

Consistent high quality makes Signode steel strapping the first choice among packaging professionals worldwide. Purchasing professionals also prefer Signode strapping because it's made to the most exacting tolerances, so it goes further and stretches their strapping dollars.

Signode offers two basic types of steel strapping: Apex, Apex Plus and Magnus. Each is specially formulated to meet the demands of a particular range of applications.

Apex[™] and Apex Plus[™] strapping

A cold-rolled, low carbon steel strapping. Manufactured with superior edge conditioning and coating.

Magnus® strapping

A cold-rolled, medium carbon steel strapping. Heat-treated with a Signode process that combines fine surface and controlled physical properties with high strength and excellent

a specific application generally depends on three factors:

perform one or more of the following functions: package reinforcement, carton closure, securement, unitization, baling, bundling, bracing, palletization, compression

Package characteristics that influence strap selection are: weight, stability, rigidity, integrity and sharpness of the edges (sharp edges may demand heavier strapping or corner protection).

choice of strapping include: how far the package is shipped; how it's handled by both the shipper and receiver; and where

Together, these various factors tend to narrow the choice to a particular set of strap characteristics. Your sales representative can help you determine your strapping requirements, such as width, thickness,

Strap Size

Apex (regular duty) strapping

inch

0.015

0.020

0.020

0.020**

0.023

0.020

0.023

0.020

0.023

Thickness

0.38

0.51

0.51

0.51

0.58

0.51

0.58

0.51

0.58

Apex Plus (regular duty high strength) strapping

Width

mm

9.5

95

12.7

12.7

15.9

15.9

190

19.0

inch

3/8

3/8

3/8

1/2

1/2

5/8

5/8

3/4

3/4

Average_

N

3 250

4 000

4 000

5 200

5 780

6 490

7 430

7 780

8 670

Strength

lhs

730

900

900

1.170

1.300

1.460

1,670

1 750

1.950

Part

085012

085003

085013

085009

085200

085203

085204

085206

085207

Yield

m/kg

35.2

26.4

26.4

19.8

17.2

15.9

13.8

132

11.5

ft/lb

54.2

39.3

393

29.4

25.6

23.6

20.5

196

17.1

SIGNODE

Strap Finish

Curved Edge

Painted & Waxed

Painted & Waxed

Curved Edge

Painted & Waxed

Coil

Weight

105

105

105

105

105

105

105

Coil

Winding

Mill

Mill

Mill

Mill

Mill

Mill

Mill

Mill

Mill

Curved Edge Painted & Waxed 0.017 0.43 2X1503 4 340 46.1 31.0 Mill 105 shock resistance. 0.017** 1/2 12.7 0.43 2X1504 1.275 5 670 346 23.3 Mill 105 Painted & Waxed The particular type of strapping best suited to 0.020 0.51 2X1270 Painted & Waxed 1/2 12.7 1.475 6 560 29.4 19.7 Mill 105 1/2 12.7 0.020 0.51 2X1174 1,475 Mill 105 6 560 29.4 19.7 Zinc 5/8 15.9 0.017** 0.43 2X1505 1.550 6 895 27.7 18.6 Mill Painted & Waxed 1) Strapping function or purpose 2) Package characteristics 5/8 15.9 0.020** 0.5 2X1253 1,825 8 120 23.6 15.8 Mill 105 Painted & Waxed 3) Shipping or handling considerations 3/4 19.0 0.017** 0.43 2X1506 1,900 8 450 23 1 15.5 Mill 105 Painted & Waxed In a specific application, strapping may 3/4 0.020** 19.0 0.51 2X1509 2.150 9 560 19.6 13.1 Mill Painted & Waxed 3/4 190 0.023 0.58 2X1551 2 500 11 120 171 11.5 Mill 105 Painted & Waxed Magnus (high tensile) strapping retention and pilferage reduction. 1/2 12.7 0.020 0.51 085604 1.540 6 850 29.4 19.7 Mill Painted & Waxed 0.020** 085644 1,920 23.6 Mill 5/8 15.9 0.51 8 540 15.8 105 Painted & Waxed 0.023 0.58 088432 5/8 15.9 2.200 9 790 20.5 13.7 Mill 105 Painted & Waxed 3/4 19.0 0.020 0.51 089397 2,250 10 230 19.6 13.1 Mill 105 Painted & Waxed Shipping considerations that affect the 19 0 0.023 0.58 089370 2 600 17 1 105 3/4 11 740 11.5 Mill Painted & Waxed 3/4 19.0 0.025** 0.64 085684 2,800 12 450 15.7 10.5 Mill 105 Painted & Waxed and how it's stored. 3/4 19.0 0.025** 0.64 085680 2,800 12 450 15.7 10.5 Ribbon 75 Painted & Waxed 3/4 19.0 0.025 0.64 076310 2.800 12 450 15.7 10.5 105 Zinc 3/4 19.0 0.029 0.74 2X1424 3.350 14 900 13.5 9.1 Mill 105 Painted & Waxed 3/4 19.0 0.029** 0.74 2X1295 3.400 15 125 13.5 9.1 Ribbon 75 Painted & Waxed finish, type of steel and tensile strength. 1-1/4 31.8 0.025 0.64 089367 4.800 21 350 9.4 6.3 Ribbon 110 Painted & Waxed 1-1/4 31.8 0.029 0.74 2X1268 5,600 24 910 8.1 5.5 Ribbon 110 Painted & Waxed 0.74 2X1296 1-1/4 31.8 0.029 5.600 25 000 5.5 Ribbon 110 1-1/4 31.8 0.031 0.79 085730 5,650 25 132 6.5 4.3 Ribbon 110 Painted & Waxed 1-1/4 31.8 0.035 0.89 0X4985 6,660 29 630 67 4.5 Ribbon 110 Painted & Waxed * Strap break strengths are listed as averages. Always use 1-1/4 31.8 0.044 1.12 2X1438 8,450 37 590 5.3 3.5 Ribbon 110 Painted & Waxed 2 50.8 0.044 2X1439 13,200 58 720 3.3 2.2 Ribbon Painted & Waxed 1.12 proper strap selection, contact your Signode sales representative. ** 300 ft. demonstration coils are available for these sizes.

American Society for Testing Materials (ASTM D-3953) minimum break strengths for package design/safety factor purposes. For